

APPLICABILITY: 2002MY Legacy Vehicles SUBJECT: Legacy VIN Scheme NUMBER: 01-153-01 DATE: 09/01/01

A small number of 2002MY Legacy Outback vehicles were produced with a Vehicle Identification Number (VIN) scheme that is not consistant with the typical VIN scheme for this model. This variation does not affect any regulatory compliance, but may present some confusion if using only the last six (6) digits (Sequential Number) of the VIN for model identification.

In the past, the Sequential Number identified Outback Wagons in the "600001 and after" range. The Legacy Wagon was identified in the "300001 and after" range. For the 2002MY, *some* Outback Wagons will be included in the Legacy Wagon range of "300001 and after."

To identify a Legacy Wagon from an Outback Wagon, use position 7 (Model Type / Trim Level) from the full 17 character VIN. Numbers 3, 4, and 5 refer to Legacy Wagons. Numbers 6, 7, 8, 9 and 0 refer to Outback Wagons.

Review the attached VIN scheme for 2002MY Legacy vehicles.



CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

