

Mainshaft

Index



Before assembling, clean all parts in solvent, dry them with compressed air, then coat them with clean oil.

* Mark parts: H2U5, H2C4 only.

