




## INSPECTION

### INSPECT SENSOR RESISTANCE

Measure resistance between terminals.

**Standard resistance:  $1,700 \pm 85 \Omega$  at  $25^{\circ}\text{C}$  ( $77^{\circ}\text{F}$ )**

If resistance is not as specified, replace the sensor.