




INSPECTION

INSPECT SENSOR RESISTANCE

Measure resistance between terminals.

Standard resistance: $1,700 \pm 85 \Omega$ at 25°C (77°F)

If resistance is not as specified, replace the sensor.