

## DIAGNOSTIC TROUBLE CODE CHART

| DTC No.<br>(See page) | Detection Item                         | Trouble Area                                                                                                                                       |
|-----------------------|----------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|
| B2795<br>(DI-732)     | Unmatched key code                     | <ul style="list-style-type: none"> <li>• Key</li> <li>• Unregistered key inserted before</li> </ul>                                                |
| B2796<br>(DI-733)     | No communication in immobiliser system | <ul style="list-style-type: none"> <li>• Key</li> <li>• Transponder key coil</li> <li>• Amplifier</li> <li>• Wirehanness</li> <li>• ECM</li> </ul> |
| B2797<br>(DI-735)     | Communication malfunction No.1         | <ul style="list-style-type: none"> <li>• Communication contents</li> <li>• Unregistered key inserted before</li> </ul>                             |
| B2798<br>(DI-736)     | Communication malfunction No.2         | <ul style="list-style-type: none"> <li>• Key</li> <li>• Transponder key coil</li> <li>• Amplifier</li> <li>• Wire haness</li> <li>• ECM</li> </ul> |

### HINT:

To reduce the unnecessary exchange of ECM, check that a trouble occurs with the original ECM at the time of exchanging ECM and the trouble will disappear with a new ECM.