

DIAGNOSTIC TROUBLE CODE CHART

DTC No. (See page)	Detection Item	Trouble Area
B2795 (DI-736)	Unmatched key code	• Key • Unregistered key inserted before
B2796 (DI-737)	No communication in immobiliser system	• Key • Transponder key coil • Amplifier • Wirehanness • ECM
B2797 (DI-739)	Communication malfunction No.1	• Communication contents • Unregistered key inserted before
B2798 (DI-740)	Communication malfunction No.2	• Key • Transponder key coil • Amplifier • Wire haness • ECM

HINT:

To reduce the unnecessary exchange of ECM, check that a trouble occurs with the original ECM at the time of exchanging ECM and the trouble will disappear with a new ECM.