

34. DVD magazine will not be ejected.

INSPECTION PROCEDURE

1 Is auto search button of radio operating normally?

Yes

Go to step 5.

No

2 Check if RADIO fuse is OK?

NG

Replace fuse.

OK

3 Is power supplied to +B terminal of power amplifier?

No

+B wire harness faulty.

YES

4 Is power supplied to +B terminal of radio receiver?

No

Power amplifier faulty.

YES

Radio assembly faulty.

5	Is power supplied to +B terminal of DVD auto changer?
---	---

No

Radio assembly faulty.

Yes

DVD auto changer faulty.