



STARTER COMPONENTS


ST08Y-01




B04884



2001 LEXUS LX470 (RM802U)



Magnetic Switch Assembly



◆ Non-reusable part

B04547