

31. Power coming in, but DVD auto changer not operating

INSPECTION PROCEDURE

1 Is DVD inserted with correct side up?

NO

Insert correctly.

YES

2 Function OK if different DVD magazine inserted?

YES

DVD magazine faulty.

NO

3 Is radio operating normally?

YES

Go to step 7.

NO

4 Does continuity exist in speaker wire harness?

NO

Speaker wire harness faulty.

YES

5	Temporarily install another speaker. Function OK?
YES Speaker faulty.	
NO	
6	Hiss noise from speaker?
NO Power amplifier faulty. Recheck system after repair.	
YES	
Radio assembly faulty. Recheck system after repair.	
7	Is temperature inside cabin hot?
YES Protective circuit in operation.	
NO	
8	Has sudden temperature change?
YES Formation of condensation due to temp. changes.	
NO	
DVD auto changer faulty.	