

32. Sound jumps

INSPECTION PROCEDURE

1 Does sound jump only during strong vibration?

Yes

Jumping caused by vibration.

No

2 Is DVD auto changer properly installed?

No

Install properly.

Yes

3 Functions OK if another CD is played?

Yes

CD faulty.

No

4 Has sudden temperature change occurred inside cabin?

Yes

Formation of condensation due to temp. changes.

No

DVD auto changer faulty.