

DIAGNOSTIC TROUBLE CODE CHART

DTC No. (SEE PAGE)	Circuit Inspection	Trouble Area
B2780 (DI-1051)	Key unlock warning switch malfunction	• Key unlock warning switch • Wire harness
B2784 (DI-1054)	Transponder key coil malfunction	Transponder key amplifier with coil
B2793 (DI-1055)	Transponder chip malfunction	Key
B2794 (DI-1056)	Unmatched encryption code	• Key • Transponder key amplifier
B2795 (DI-1057)	Unmatched key code	• Key • Unregistered key inserted before
B2796 (DI-1058)	No communication in immobiliser system	• Key • Transponder key amplifier with coil • Wire harness • Transponder key ECU
B2797 (DI-1060)	Communication malfunction No.1	• Key • Wire harness • Transponder key amplifier with coil • Transponder key ECU
B2798 (DI-1063)	Communication malfunction No.2	• Key • Transponder key amplifier with coil • Wire harness • Transponder key ECU
B2799/99 (DI-1066)	Engine immobiliser system malfunction	• Wire harness • Transponder key ECU • ECM

HINT:

To reduce the unnecessary exchange of Transponder key ECU, check that a trouble occurs with the original Transponder key ECU at the time of exchanging Transponder key ECU and the trouble will disappear with a new Transponder key ECU.