

4. No corresponding screen displayed when "Audio" or "Information" switch pressed.

INSPECTION PROCEDURE

1 Display check mode (Panel switch check mode screen)

NG

Troubleshoot for each diagnosis.

OK

2 Check AVC-LAN communication circuit (See page [DI-1668](#)).

NG

Repair or replace AVC-LAN circuit.

OK

Replace the multi display.