

97V072000: FUEL FILLER TUBE

1992 Infiniti G20

NHTSA RECALL BULLETIN

Model(s): 1991-96 Infiniti G20
Campaign No: 97V072000
Number of Affected Vehicles: 85000
Beginning Date of Manufacture: 1990 JUL
Ending Date of Manufacture: 1996 MAY

DESCRIPTION OF DEFECT:

Corrosion of the fuel filler tube assembly can occur, especially those vehicles operated in the "Salt Belt," resulting in fuel leakage.

CONSEQUENCE OF DEFECT:

Fuel leakage in the presence of an ignition source can result in a fire.

CORRECTIVE ACTION:

Dealers will inspect the fuel filler tube and replace the tube with a new one. Any other components of the fuel filler tube assembly which are damaged or deteriorated will also be replaced.

OWNER NOTIFICATION:

Owner notification is expected to begin during June 1997.

Owners who take their vehicles to an authorized dealer on an agreed upon service date and do not receive the free remedy within a reasonable time should contact Nissan at 1-800-647-7261. Also contact the National Highway Traffic Safety Administration's Auto Safety Hotline at 1-800-424-9393.

ADDITIONAL INFORMATION:

The National Highway Traffic Safety Administration operates Monday through Friday from 8:00 AM to 4:00 PM, Eastern Time. For more information call (800) 424-9393 or (202) 366-0123. For the hearing impaired, call (800) 424-9153.