



NISSAN MOTOR CORPORATION IN U.S.A.

Post Office Box 191
Gardena, California 90248
Telephone: (310) 532-3111

TECHNICAL DATABASE INFORMATION

Record ID: FC0007692	Source Reference Number: STC196	Classification: SEPT 92
Subject: ABS LIGHT CODE4	Entered On: 09/18/92	
Model Line: PTH 720	Model Year: 91 92 93	

Technical Information Abstract:

INFORMATION: ABS EQUIPPED D21 PICK UPS AND PATHFINDERS WITH REPORTED ABS WARNING LIGHT ON INTERMITTENTLY OR CONTINUOUSLY SHOWING CODE 4.

FIELD FIX: REFER TO SERVICE MANUAL PAGE BR-52 AND CHECK GROUND CONTINUITY AT ABS ELECTRONIC CONTROL UNIT TERMINAL NUMBER FOUR (4). IF CONTINUITY EXISTS BETWEEN TERMINAL 4 AND THE BODY GROUND, REPLACE ABS ACTUATOR ASSEMBLY. IF NO CONTINUITY EXISTS BETWEEN TERMINAL 4 OF THE ABS ECU AND BODY GROUND, INSPECT HARNESS AND CONNECTIONS FOR OPEN OR SHORT. REPLACE OR REPAIR AS REQUIRED.

Index : 032045