



NISSAN MOTOR CORPORATION IN U.S.A.

Post Office Box 191
Gardena, California 90248
Telephone: (310) 532-3111

TECHNICAL DATABASE INFORMATION

Record ID: FC0007827	Source Reference Number: FI76175	Classification: OCT '92
Subject: DASH SQUEAK	Entered On: 10/21/92	
Model Line: PTH	Model Year: 91 92 93	

Technical Information Abstract:

INFO SOURCE: AUGIE, WESTBURY NISSAN, LTD., NY.

SYMPTOMS: SQUEAK FROM LEFT SIDE OF DASH. OCCURS AT LOW SPEEDS OF 10-25 MPH.
'92 PTH COULD DUPLICATE INCIDENT BY BOUNCING VEHICLE UP AND DOWN. VERIFIED
THAT NOISE IS NOT RELATED TO WINDSHIELD MOULDINGS.

FIELD FIX: FOUND THE LEFT FRONT FENDER WAS RUBBING AGAINST THE COWL AND WIND-
SHIELD. THE FENDER WAS NOT FULLY TRIMMED OF EXCESS MATERIAL ALONG
THE EDGES WHERE THE FENDER, WINDSHIELD AND COWL MEET. BENT THE
EDGE OF THE FENDER AWAY FROM COWL AND WINDSHIELD TO RESOLVE.

Index # 032082