



NISSAN MOTOR CORPORATION IN U.S.A.

Post Office Box 191
Gardena, California 90248
Telephone: (310) 532-3111

TECHNICAL DATABASE INFORMATION

Record ID:	Source Reference Number:	Classification:
FC0008541	BBS	JUN '93
Subject:	Entered On:	
IDLE FLUCTUATES	06/03/93	
Model Line:	Model Year:	
NIS	90 91 92 93 94	

Technical Information Abstract:

INFORMATION: IF YOU HAVE A VEHICLE THAT EXHIBITS AN INCIDENT OF FLUCTUATING
ALL MODELS IDLE, PLEASE MAKE THE FOLLOWING INITIAL CHECKS:
& YEARS W/
ECCS SYSTEM

- 1) CHECK/SET BASE IDLE SETTING
- 2) CHECK/ADJUST TPS SETTING
- 3) TPS IDLE VOLTAGE STABILITY SHOULD BE 'ROCK STEADY'--IF NOT, CHECK HARNESS SPLICE FOR TPS, AND WATER TEMP SENSOR GROUND.
- 4) CHECK THROTTLE CHAMBER/THROTTLE PLATE FOR BINDING OR BEING GUMMED UP.

NOTE: PLEASE REFER TO THE EF & EC SECTION FOR BASE IDLE AND TPS SETTING PROCEDURES AND SPECIFICATIONS IN THE APPROPRIATE SERVICE MANUAL.

Index # 034853