

## SERVICE BULLETIN

**APPLICABILITY** ALL SUBARU VEHICLES

**DATE** 2/23/96

**SUBJECT** Removal of protective plastic seat covers

The seats of all new Subaru vehicles are covered with a clear plastic protective covering to protect the seats from becoming soiled during shipment from the manufacturing facility to the dealership. This clear plastic covering must be removed from the seats by the dealer during the Pre-Delivery Inspection, prior to delivery of the vehicle to the retail purchaser or prior to use of the vehicle in demonstrator service to conform to applicable Federal Motor Vehicle Safety Standards.

**CAUTION**

**VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.**

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.