

ATTENTION:

GENERAL MANAGER
 PARTS MANAGER
 CLAIMS PERSONNEL
 SERVICE MANAGER

IMPORTANT - All
 Service Personnel
 Should Read and
 Initial in the boxes
 provided, right.

QUALITY DRIVEN® SERVICE



SUBARU

SERVICE BULLETIN

APPLICABILITY: 2007~08MY Legacy/Outback
SUBJECT: Parking Brake Lever Boot and Manual
 Transmission Shift Lever Boot

NUMBER: 03-56-07
 06-38-07
DATE: 09/07/07

INTRODUCTION

If you encounter a customer complaint of cracks in the leather parking brake lever boot and/or manual transmission shift lever boot, a modification was made to improve the durability of the leather. This Service Bulletin informs of the new part numbers.

PRODUCTION LINE CHANGE

The countermeasure parts were used in production August, 2007 with the following VINs:

MODEL	BODY	STARTING VIN
Legacy	Sedan	8*210730
	Wagon	8*326714
Outback		8*326469

PART INFORMATION

Parking Brake Lever Boot

COLOR	PART NUMBER
Ivory	92123AG11BWA
Off Black	92123AG11BJC

Shift Lever Boot

TRANS TYPE	PART NUMBER
6MT	92121AG10B
5MT	92121AG13B
5MT SI-Drive	92121AG56B

WARRANTY INFORMATION

For vehicles under the Basic New Car Limited Warranty period, refer to the Subaru Warranty Wizard for claim submission information.

CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.

Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.

