

Front Accessory Power Supply Socket System





WIRING SYSTEM

41. Front Accessory Power Supply Socket System

A: WIRING DIAGRAM

FAPS-01

FAPS-01



WI-16083