

DIAGNOSTIC TROUBLE CODE CHART

DTC No. (See page)	Detection Item	Trouble Area
B2785 (DI-754)	Ignition switch ON malfunction	• Ignition Switch • Main Relay • Wireharness
B2786 (DI-754)	Ignition switch OFF malfunction	
B2791 (DI-758)	Key unlock warning switch OFF malfunction	• Key unlock warning switch • Main Relay • Wireharness
B2795 (DI-760)	Unmatched key code	• Key • Unregistered key inserted before
B2796 (DI-761)	No communication in immobiliser system	• Key • Transponder key coil • Amplifier • Wireharness • Engine and ECT ECU
B2797 (DI-763)	Communication malfunction No.1	• Communication contents • Unregistered key inserted before
B2798 (DI-765)	Communication malfunction No.2	• Key • Transponder key coil • Amplifier • Wire harness • Engine and ECT ECU

HINT:

To reduce the unnecessary exchange of Engine and ECT ECU, check that a trouble occurs with the original Engine and ECT ECU at the time of exchanging Engine and ECT ECU and the trouble will disappear with a new Engine and ECT ECU.