

DIAGNOSTIC TROUBLE CODE CHART

DTC No. (See page)	Detection Item	Trouble Area
B2785 (DI-566)	Ignition switch ON malfunction	• Ignition switch • Main relay • Wireharness
B2786 (DI-566)	Ignition switch OFF malfunction	
B2791 (DI-570)	Key unlock warning switch OFF malfunction	• Key unlock warning switch • Main Relay • Wireharness
B2795 (DI-572)	Unmatched key code	• Key • Unregistered key inserted before
B2796 (DI-573)	No communication in immobiliser system	• Key • Transponder key coil • Amplifier • Wireharness • ECM
B2797 (DI-575)	Communication malfunction No.1	• Communication contents • Unregistered key inserted before
B2798 (DI-577)	Communication malfunction No.2	• Key • Transponder key coil • Amplifier • Wire harness • ECM

HINT:

To reduce the unnecessary exchange of ECM, check that a trouble occurs with the original ECM at the time of exchanging ECM and the trouble will disappear with a new ECM.