

30 DVD magazine inserted, but no power.

INSPECTION PROCEDURE

1 Is radio operating normally?

YES

Go to step 5.

NO

2 Check CIGER fuse is OK?

NG

Replace fuse.

OK

3 Is power supplied to ACC terminal of stereo component amplifier?

NO

ACC wire harness faulty.

YES

4 Is power supplied to ACC terminal of radio receiver assembly?

NO

Stereo component amplifier faulty.

YES

Radio receiver assembly faulty.

5	Is power supplied to ACC terminal of DVD auto changer?
---	--

NO**Radio receiver assembly faulty.****YES****DVD auto changer faulty.**