


## E ELECTRICAL WIRING ROUTING

### Position of Parts in Instrument Panel

[LHD]



J 1 Junction Connector  
 J 2 Junction Connector  
 J 3 Junction Connector  
 J 4 Junction Connector  
 J 5 Junction Connector  
 J 6 Junction Connector  
 J 7 Junction Connector  
 J 8 Junction Connector  
 J 9 Junction Connector  
 J 10 Junction Connector  
 J 11 Junction Connector  
 J 12 Junction Connector  
 J 13 Junction Connector  
 J 14 Junction Connector  
 J 15 Junction Connector  
 J 16 Junction Connector  
 J 17 Junction Connector  
 J 18 Junction Connector

J 19 Junction Connector  
 J 20 Junction Connector  
 J 24 Junction Connector  
 J 25 Junction Connector  
 J 26 Junction Connector  
 J 27 Junction Connector  
 J 28 Junction Connector  
 J 29 Junction Connector  
 J 30 Junction Connector

M 4 Multi-Display  
 M 5 Multi-Display  
 M 6 Multi-Display

O 2 O/D Main SW

P 3 Power Outlet (Front)  
 P 6 Pre-Heating Timer