


E ELECTRICAL WIRING ROUTING

Position of Parts in Instrument Panel

[RHD]



* 3:A/T
 * 5:M/T Bench Seat
 * 6:M/T Separate Seat
 *18:1HZ

J 1 Junction Connector
 J 3 Junction Connector
 J 4 Junction Connector
 J 5 Junction Connector
 J 6 Junction Connector
 J 7 Junction Connector
 J 8 Junction Connector
 J 9 Junction Connector
 J 10 Junction Connector
 J 11 Junction Connector
 J 12 Junction Connector
 J 13 Junction Connector
 J 14 Junction Connector
 J 15 Junction Connector
 J 16 Junction Connector
 J 17 Junction Connector
 J 18 Junction Connector
 J 19 Junction Connector

J 20 Junction Connector
 J 21 Junction Connector
 J 22 Junction Connector
 J 24 Junction Connector
 J 25 Junction Connector
 J 26 Junction Connector
 J 27 Junction Connector
 J 29 Junction Connector
 J 30 Junction Connector

M 4 Multi-Display
 M 5 Multi-Display
 M 6 Multi-Display

O 2 O/D Main SW

P 3 Power Outlet (Front)
 P 6 Pre-Heating Timer