

RAIN SENSOR SYSTEM

HOW TO PROCEED WITH TROUBLESHOOTING

DIAYV-01

HINT:
This ECU is connected to the multiplex communication system. Therefore, be sure to check that there is no trouble in the multiplex communication system before performing the troubleshooting.

