

## 30. Sound jumps (DVD sound only).

### INSPECTION PROCEDURE

1 Does sound jump only during strong vibration?

Yes

Jumping caused by vibration.

No

2 Is DVD auto changer properly installed?

No

Install properly.

Yes

3 Functions OK if another DVD is played?

Yes

DVD faulty.

No

4 Has sudden temperature change occurred inside cabin?

Yes

Formation of condensation due to temp. changes.

No

Check and replace DVD auto changer.