


E ELECTRICAL WIRING ROUTING

Position of Parts in Instrument Panel

[RHD]



J 1 Junction Connector
J 3 Junction Connector
J 4 Junction Connector
J 5 Junction Connector
J 6 Junction Connector
J 7 Junction Connector
J 8 Junction Connector
J 9 Junction Connector
J 10 Junction Connector
J 11 Junction Connector
J 12 Junction Connector
J 13 Junction Connector
J 14 Junction Connector
J 15 Junction Connector
J 16 Junction Connector
J 17 Junction Connector
J 19 Junction Connector

J 21 Junction Connector
J 22 Junction Connector
J 24 Junction Connector
J 25 Junction Connector
J 26 Junction Connector
J 27 Junction Connector
J 28 Junction Connector
J 29 Junction Connector
J 30 Junction Connector

K 3 Key Interlock Solenoid

M 4 Multi-Display
M 5 Multi-Display

P 3 Power Outlet (Front)
P 6 Pre-Heating Timer

* 3:A/T
* 5:M/T Bench Seat
* 6:M/T Separate Seat
*18:1HZ