

PRECAUTIONS

Be careful not to grip the propeller shaft tube too tightly in the vise as this will cause deformation.

TROUBLESHOOTING

You will find the cause of trouble more easily by properly using the table shown below. In this table, the numbers indicate the priority of the probable cause of trouble. Check each part in the order shown. If necessary, repair or replace the part.

Problem	Possible cause	Remedy	Page
Noise	Sleeve yoke spline worn Spider bearing worn or stuck	Replace sleeve yoke Replace spider bearing	PR-6 PR-6
Vibration	Propeller shaft runout Propeller shaft imbalance Sleeve yoke spline stuck	Replace propeller shaft Balance propeller shaft Replace sleeve yoke	PR-5 PR-6