

TROUBLESHOOTING

TROOQ-01

Problem	Possible cause	Remedy	Page
Hard to shift or will not shift	Transfer faulty	Disassemble and inspect transfer	TF-9
Transfer jumps out of gear	Transfer faulty	Disassemble and inspect transfer	TF-9

V01482