

HEAT INSULATOR INSPECTION

1. CHECK HEAT INSULATOR FOR DAMAGE
2. CHECK FOR ADEQUATE CLEARANCE BETWEEN TWC AND HEAT INSULATOR

FRONT TWC AND REAR TWC REPLACEMENT

(See exhaust system in Engine Mechanical)

SERVICE SPECIFICATIONS

SERVICE DATA

VSV for EVAP	Resistance	at 20°C (68°F)	30–34Ω
--------------	------------	----------------	--------

TORQUE SPECIFICATIONS

Part tightened	N·m	kgf·cm	ft·lbf
Charcoal canister x Charcoal canister bracket	14	145	10
Charcoal canister bracket x Body	18	185	13
TVV x Cylinder head	29	300	22
Intake manifold stay x Air intake chamber	36	360	26
Intake manifold stay x Cylinder block	36	360	26
EGR valve x Air intake chamber for stud bolt	9	90	78 in.-lbf
EGR valve x Air intake chamber or nut	18	180	13
EGR valve x EGR pipe	64	650	47
EGR valve x EGR vacuum modulator	18	185	13