
■OUTSIDE REARVIEW MIRROR

1. GENERAL

On models for Vietnam, The Philippines, Thailand, Indonesia and Malaysia, outside rearview mirrors have been adopted which are coated with a hydrophilic film that effectively removes water drops from the mirror surface through a hydrophilic effect in order to ensure rear visibility in the rain.


2. Construction

The rain-clearing mirror that is coated on the mirror consists of two films: silicon dioxide (SiO2) and titanium dioxide (TiO2).
The silicon dioxide film bonds with the water the drops that are adhered onto the mirror surface, thus expanding the water into film shape (through the hydrophilic effect). As a result, the hydrophilic performance of the mirror surface is ensured.
Through the chemical reaction that occurs as the ultraviolet rays are cast upon it, the titanium dioxide film breaks down the smudges, such as oil, that are adhered onto the silicon dioxide film in order to prevent the mirror surface from becoming dirty.



■CHILD RESTRAINT SYSTEM

ISO-FIX bar for securing child seats has been provided behind the seat cushion of the rear seat.
Three CRS anchor brackets for securing a child seat are provided above the package tray trim.



*1: Used on Chinese models
*2: CRS Anchor Bracket is used on models for China, Australia, G.C.C. Countries
*3: Used on Australian and G.C.C. Countries 2AZ-FE engine models
*4: Used on Australian and G.C.C. Countries 2GR-FE engine models and Chinese models