
■ LOW VIBRATION AND LOW NOISE BODY

- Rear engine service cover weatherstrip have been adopted in the engine service hole cover. Its cross sectional shape reduces noise transmitted from the engine to the vehicle interior.




0479BO68

► **Text in Illustration** ◄

*1	Rear Engine Service Cover Weatherstrip	*2	Engine Service Hole Cover
*a	A - A Cross Section	*b	Engine Section
*c	The illustrations shown are examples only.	-	-


- Floor panels have been adopted on the floorboard over the transmission to improve soundproofing for vehicles equipped with the engine of N04C series.





► Text in Illustration ◄


*A	Models with Floor Panel	-	-
*1	Floor Panel (No. 4 Rear Floor Board Panel)	*2	Floor Panel (No. 1 Rear Floor Board Panel)
*3	Floor Panel (No. 5 Rear Floor Board Panel)	-	-
*a	The illustrations shown are examples only.	*b	Transmission Section

- Opening weatherstrips have been adopted in the glide type center door, luggage type back door, and double-leaf type back door to improve sealing of the doors.









*a *b *c

*d

► Text in Illustration ◄

*1	Opening Weatherstrip (Glide Door Side Weatherstrip)	*2	Glide Door Glass
*3	Opening Weatherstrip (Back Door Weatherstrip)	*4	Outer Back Door Panel
*5	Back Door Glass	-	-
*a	A - A Cross Section	*b	B - B Cross Section
*c	C - C Cross Section	*d	The illustrations shown are examples only.