
MAP DISPLAY INCOMPLETE

INSPECTION PROCEDURE

1	CHECK THE MAP DISC



(a) Check that the map disc is not deformed or cracked.
OK: No deformations or cracks appear on the map disc.

NG → **REPLACE THE MAP DISC**

OK

2	CHECK THE DISPLAY

(a) Check that displays other than the navigation display are complete.
OK: No other incomplete displays are found.

OK → **REPLACE NAVIGATION ECU (SEE PAGE 05–1570)**

NG

PROCEED TO NEXT CIRCUIT INSPECTION SHOWN IN PROBLEM SYMPTOMS TABLE (SEE PAGE 05–1570)