

TURNING ON LIGHT SWITCH DOES NOT LIGHT UP NIGHT TIME ILLUMINATION OF RADIO RECEIVER

WIRING DIAGRAM



INSPECTION PROCEDURE

1	CHECK RADIO RECEIVER ASSY (ILL+)



(a) Remove the radio receiver with the connectors still connected.

(b) Check the voltage between the terminals of the R1 connector.

Standard:

Symbols (Terminal No.)	Condition	Specified Condition
ILL+ (R1–10) ⇔ GND (R1–7)	light control switch TAIL	20 – 28 V

NG → **REPAIR OR REPLACE HARNESS AND CONNECTOR**

OK

REPAIR OR REPLACE RADIO RECEIVER ASSY