





# SERVICE BULLETIN

PUBLICATION GROUP, AFTER SALES SERVICE DEP.  
MITSUBISHI MOTOR SALES EUROPE BV

<b>SERVICE BULLETIN</b>		No.: ESB-99E54-504	
		Date: 1999-12-15	<Model> <M/Y>
<b>Subject:</b> CORRECTION TO FUEL PUMP CHECK CONNECTOR NO.		(EC, EXP)	98-10
<b>Group:</b> CHASSIS ELECTRICAL		CARISMA	
<b>CORRECTION</b>		 O. Kai - E.V.P. & G.M. After Sales Service Dept.	
<b>1. Description:</b>			
In the '98 CARISMA GDI Electrical Wiring manual, the incorrectness of the fuel pump check connector No. Has been rectified.			
<b>2. Applicable Manuals:</b>			
<b>Manual</b>	<b>Pub. No.</b>	<b>Language</b>	<b>Page(s)</b>
'98 CARISMA GDI Electrical Wiring	PHDE9501-C	(English)	2-3
	PHDS9502-C	(Spanish)	
	PHDF9503-C	(French)	
	PHDG9504-C	(German)	
	PHDD9505-C	(Dutch)	
	PHDW9506-C	(Swedish)	
	PHDI96E1-C	(Italian)	
<b>3. Details:</b>			



- |             |  |             |                               |
|-------------|--|-------------|-------------------------------|
| A-32 (2-B)  | Radiator fan motor   | A-44 (2-G)  | Headlamp washer motor         |
| A-33 (10-B) | Inhibitor switch   | A-45 (2-G)  | Rear washer motor             |
| A-34 (4)    | Condenser fan motor  | A-46 (2)    | Windshield washer motor       |
| A-35 (2)    | Outside thermo sensor <Full-auto A/C><br>or no connection <Manual A/C> | A-47 (2-B)  | Front turn signal lamp (RH)   |
| A-36 (1)    | Power steering oil pressure switch                                     | A-48 (31)   | ABS-ECU                       |
| A-37 (2-B)  | Position lamp (RH)   | A-49 (2-B)  | Front speed sensor (RH) <ABS> |
| A-38 (3-B)  | Headlamp (RH)  | A-50 (2-B)  | Side turn signal lamp (RH)    |
| A-39 (3-B)  | Headlamp leveling unit (RH)  | A-51 (2-GR) | Injector No. 1                |
| A-40 (2-G)  | Front fog lamp (RH)  | A-52 (2-GR) | Injector No. 2                |
| A-41 (2-B)  | Horn (RH)  | A-53 (2-GR) | Injector No. 3                |
| A-43 (2-BR) | Washer fluid level sensor  | A-54 (2-GR) | Injector No. 4                |