

## **Service Bulletin List**

No.	Subject	Date
MSB-97E26-002	ADDITION OF FRONT AXLE SHIM TO DRIVE SHAFT	1997-09-26
MSB-97E35-005	CHANGE IN LIMIT VALUE FOR FRONT BRAKE DISC RUN-OUT	1998-05-15
MSB-97E52-001	ADDITION OF SRS AIR BAG MAINTENANCE PROCEDURE	1997-04-30
MSB-97E55-001	CHANGE IN AIR GAP FOR A/C COMPRESSOR	1998-04-15
MSB-98E00-001	YEAR MODEL CHANGES FOR '98 MODEL LANCER WAGON	1998-05-15