


# insider info.

## Shifter Rattle

If you encounter a shifter rattle complaint on a 1996/97 Legacy Outback or on a 1998 Forester, the necessary parts are available to correct this symptom.

For the 1996 Legacy Outback, order a modified spacer, P/N 35045AC040.



1996 Legacy Spacer

For the 1998 Forester or 1997 Legacy, order a modified bolt, P/N 35045FC000.

