


CHARGING SYSTEM

WIRING SYSTEM

12. Charging System A: SCHEMATIC

CHARGE-01

CHARGE-01



F26 (GREEN)

1	2	3
---	---	---

C: i12 (GREEN)

1	2	3	4	5	6		
7	8	9	10	11	12	13	14

B228

1	2	3			
4	5	6	7	8	9
10	11	12	13	14	15

F2 (BLUE)

1	2	3	4	5	6	7	8
9	10	11	12	13	14	15	16

WI-00574