

SYSTEM WIRING DIAGRAMS

2.2L, Cooling Fan Circuit, W/O A/C

1997 Honda Accord

For DIAKOM-AUTO <http://www.diakom.ru> Taganrog support@diakom.ru (8634)315187

Copyright © 1998 Mitchell Repair Information Company, LLC

Saturday, December 23, 2000 05:05PM

