

See page [DI-670](#).

DTC No.	Detection Item	Trouble Area
P1566/ 54	• Input signal abnormal.	• ECM

Check and replace ECM (See page IN-33).