


DTC	C1761 / 61	Malfunction in ECU (Memory Error)
------------	-------------------	--

CIRCUIT DESCRIPTION

DTC No.	DTC Detecting Condition	Trouble Area
C1761 / 61	When the EEPROM of the ECU has become abnormal	• ECU internal memory error

INSPECTION PROCEDURE

1	Clear the DTC (See page DI-213).
----------	---



2	Turn the ignition switch ON and check that the DTC is not detected.
----------	--

YES

No problem.

NO

Check and replace suspension control ECU.