

21. GPS mark does not appear.

INSPECTION PROCEDURE

1

Check the mark display. (At a place with a fine view, is GPS mark displayed or not?)

Yes

Normal.

No

2

Check if the harness is caught or sharply bent or not.

NG

Navigation antenna is surely connected.

OK

3

Check optional components. (Does it become normal if the optionals such as the theft deterrent system is removed?)

Yes

Remove or change the position of the components.

HINT:

Some optionals receive radio signals, and if this happens, GPS reception may be affected.

No

4	Is there anything such as a film stuck to the window?
----------	--

Yes**Reception may be affected by a screen such as a film.****No**

5	Service check mode. (Is "80-40, 41" is displayed in the unit check mode of the navigation ECU?)
----------	--

Yes**Troubleshoot for each diagnosis.****No****Replace the navigation antenna.****HINT:**

If the trouble still occurs, replace the navigation ECU.