

DTC	B2794	Unmatched Encryption Code
------------	--------------	----------------------------------

CIRCUIT DESCRIPTION

This DTC is detected when the code decoded in the Transponder Key ECU and the code received from the key are not matched during the key code verification. Replace the key when this DTC is detected.

DTC No.	DTC Detecting Condition	Trouble Area
B2794	• Transponder chip malfunction	• Key

INSPECTION PROCEDURE

Replace key.