


DRIVER DOOR CONTROL SYSTEM

HOW TO PROCEED WITH TROUBLESHOOTING

DIBCU-01

HINT:
The ECU is connected to the multiplex communication system. Therefore, be sure to check that there is no troubles in the the multiplex communication system before performing the troubleshooting.



Step 2, 5, 10 :Diagnostic steps permitting the use of the hand-held tester.