

POWER SEAT CONTROL SYSTEM

HOW TO PROCEED WITH TROUBLESHOOTING

DIOFP-10

HINT:

ECU of this system is connected to the multiplex communication system. Therefore, before starting troubleshooting, make sure to check that there is no trouble in the multiplex communication system.

