

4. No corresponding screen displayed when "Audio" or "Information" switch pressed.

INSPECTION PROCEDURE

1	Display check mode (Panel switch check mode screen)
---	---

NG	Troubleshoot for each diagnosis.
----	----------------------------------

OK

2	Check AVC-LAN communication circuit (See page DI-1675).
---	--

NG	Repair or replace AVC-LAN circuit.
----	------------------------------------

OK

Replace the multi display.
