










CHARGING

SST (Special Service Tools)

PP42J-01

	09820-63011 Alternator Pulley Set Nut Wrench Set	
	09950-40011 Puller B Set	
	(09951-04020) Hanger 200	
	(09952-04010) Slide Arm	
	(09953-04020) Center Bolt 150	
	(09954-04010) Arm 25	
	(09955-04071) Claw No.7	
	(09958-04011) Holder	
	09950-60010 Replacer Set	
	(09951-00250) Replacer 25	
	(09951-00470) Replacer 47	
	09950-70010 Handle Set	

PREPARATION - CHARGING

	(09951-07100) Handle 100
---	--------------------------