

## 4. Spark Plug Cord S101014

### A: INSPECTION S101014A10

Check for:

- 1) Damage to cords, deformation, burning or rust formation of terminals
- 2) Resistance values of cords

#### **Resistance value:**

**#1 cord: 7.40 — 17.27**

**#2 cord: 6.24 — 14.56**

**#3 cord: 6.54 — 15.25**

**#4 cord: 6.59 — 15.37**

