

TROUBLESHOOTING

PR03H-01

PROBLEM SYMPTOMS TABLE

Use the table below to help you find the cause of the problem. The numbers indicate the priority of the likely cause of the problem. Check each part in order. If necessary, replace these parts.

Symptoms	Suspect Area	See page
Noise	1. Sleeve yoke spline worn 2. Spider bearing worn or stuck	PR-5 PR-5
Vibration	1. Sleeve yoke spline stuck 2. Propeller shaft runout. 3. Propeller shaft imbalance.	PR-5 PR-5 –