

31. Power coming in, but CD auto changer not operating

INSPECTION PROCEDURE

1 Is CD inserted with correct side up?

NO

Insert correctly.

YES

2 Function OK if different CD magazine inserted?

YES

CD magazine faulty.

NO

3 Is radio operating normally?

YES

Go to step 7.

NO

4 Does continuity exist in speaker wire harness?

NO

Speaker wire harness faulty.

YES

5 Temporarily install another speaker. Function OK?

YES

Speaker faulty.

NO

6 Hiss noise from speaker?

NO

**Power amplifier faulty.
Recheck system after repair.**

YES

Radio assembly faulty. Recheck system after repair.

7 Is temperature inside cabin hot?

YES

Protective circuit in operation.

NO

8 Has sudden temperature change?

YES

Formation of condensation due to temp. changes.

NO

CD auto changer faulty.